



Nº 9206

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Nov 3-76

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM look on inspectors Report

HOUSE NO. 973

SIZE OF PIPE USED 6


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? 5 feet behind

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Glue

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Carnation

SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 9206

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Sept. 20

RECEIVED OF

Jacob Glick

FEE OF \$25.

FOR WHICH PERMISSION IS GRANTED

Waddy Clay

TO TAP

Sanitary

SEWER ON THE

West

OF

Camerton St. NE.

AVE.

ST. TYPE OF STREET

Chip & Seal

THE PREMISES BEING LOT NO.

14063

HOUSE NO.

973

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Glick

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**