


19-34
7N^o 9213✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED Oct 2 - 78IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM80 feet @HOUSE NO. 1342SIZE OF PIPE USED 6 inchDISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH80 feet southWAS LATERAL AT CURB? 15 feet behind

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Shanbuck

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED 1/4 L
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9213

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASCILLON, OHIO,

1975

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

SIDE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.