FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 9240 AND SIGNED WHEN RETURNED DATE INSPECTED Mar 29 -78 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM..... HOUSE NO.___ 834 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH. WAS LATERAL AT CURB? 40 Pert his WAS ATTACHED TO MAIN..... 3 fective from mutheus SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. and draps down 10 feet te in 10 pert from ments to laterial 2 300 Renols of inline will Day Walland saw moil trail FILED AT ENGINEER'S OFFICE Inspector for City REMARKS _

№ 9240

OFFICE OF THE DIRECTOR OF PUBLIC SER' PERMIT TO TAP SEWER

	MASSILLON, OHIO, 1/AV: 17
RECEIVED OF MEMbrach Coffian	FEE OF \$ 35.
FOR WHICH PERMISSION IS GRANTED BELL M	ala L
TO TAP La cultury SEWE	ER ON THE
OF SILVE MILL Server 1/6. AVE. ST. TYPE	ECF STREET May & Och
THE PREMISES BEING LOT NO. 14 037	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	·
NAME OF CONTRACTOR Stinknich	

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.