№ 9287

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $10-1-79$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1018	,	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	01 0'- 5	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 9 Lick	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
29 FROM NORTH CORNER 32 OF		
)		
SIGNED FILED AT ENGINEER'S OFFICE		
inspector for only		
REMARKS		

№ 9287

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, June /
RECEIVED OF Flore Hair	FEE OF \$25.
FOR WHICH PERMISSION IS GRANTED	
TO TAP Sanctary SE	-f
of Cainchow fl. 716 AVE. ST. TY	
1/10-1	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.