FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N_{\overline{0}}$ 9302

AND SIGNED WHEN RETURNED

DATE INSPECTED 7-//-79 HOUSE NO. 2/5	IF SO HOW AND LOCATION FROM 36 FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? MANHOLE A	TREAR OF HOUSE
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HOLESANDER
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
2/575,5	FRONT
House	L. Rear
N 27 mon 3'2" Down at comer Hope 36' Pige	of the state of th
1450 Bend 100 1/1 Dec	\mathcal{P}
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9302

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, July 3			
RECEIVED OF Nalduba	uzel		<u> </u>	FEE OF \$ 15.
FOR WHICH PERMISSION IS GRANTED Jay	D. Wille	÷		
FOR WHICH PERMISSION IS GRANTED			· · · · · · · ·	
TO TAP Sanitary	SEWER ON THE.	//	Kuit	·
OF 21 th Sc.	AVE. _ST. TYPE (F STREET	. Chip	9 Se	J. C.
THE PREMISES BEING LOT NO. 6329 \$ 6		- i		
WORK TO BE DONE IN ACCORDANCE WITH ORDIN				
OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR Haldicha	come			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.