

1-5

Nº 9314

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8-21-79

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 25'

HOUSE NO. 427

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 3" BEHIND SIDEWALK

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR James Lewis

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS 33' FROM CLEANOUT TO 300' BEHIND 1' IN FROM BEHIND W

REPAIR

Nº 9314

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Aug. 21

RECEIVED OF

James Lewis

FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED

American Legion

REPAIR

TO-TAP

Sanitary

SEWER ON THE

South

OF

N. W. E

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

279

HOUSE NO.

427

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Lewis

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.