



Nº 9319

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-27-79

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1244

SIZE OF PIPE USED


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? N/A

WAS ATTACHED TO MAIN STUB TO MH

NAME OF CONTRACTOR MALAVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Tom D. Leub  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS One Cracked lateral

Nº 9319

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 27

RECEIVED OF Melanite Contracting FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED KeyStone Bldg. (Guyana Bldg.)

TO TAP Sanitary SEWER ON THE North

OF Lincoln Way, W. AVE. ST. TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 0-115, HOUSE NO. 1244

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Melanite

**Note:** This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.