## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 9322 AND SIGNED WHEN RETURNED

DATE INSPECTED 3-2/-79	IF SO HOW AND LOCATION FROM
DATE MAREOLEDIZIONES	FIRST MANHOLE DOWN STREAM
HOUSE NO. /3 - / 9	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Portugia i
WAS ATTACHED TO MAIN.	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	
[NO7/3] [3	WO-1- Y'FROM
01	WER DE BUILDING WEST
24/EROM	
FACT CURNER	
, う - こ フィニ <i>カイ</i> ル G	,
SIGNED.	FILED AT ENGINEER'S OFFICE
Inspector for Cit	ÿ ;
REMARKS	

 $N^{0}$  9322

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON.	OHIO,	legit.	13
RECEIVED OF Daniel Colory &	Lows	۷	/ 	FEE OF \$ ) 16 7
FOR WHICH PERMISSION IS GRANTED CM	Marci	ellor		
FOR WHICH PERMISSION IS GRANTED OF TO TAP Sanday SEW	JER ON THE	- Jack-	والمجارين والمتاركين	
of Teconet du S. W. AVE. ST. TYP				ace
THE PREMISES BEING LOT NO. # 05 4 1/69	·	HOUSE NO	13-3	19
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	. <b>19</b> -19 <b>7</b> 1 🗅	DULY PASSED	BY THE CITY	COUNCIL, AND RE
NAME OF CONTRACTOR Calculation				
Note: This paymit covers work of	ontsida a	f buildin	or only	Any work i

walls of building is subject to Massillon Board of Health Regulations.