

Nº 9325

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-79

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

26'

HOUSE NO. 209

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

26'

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

A. J. DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ST. JAMES A.M.E. CHURCH



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 9325

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 27*

RECEIVED OF

A. J. Liane Sons Inc.

FEE OF \$

75.00

FOR WHICH PERMISSION IS GRANTED

to James A. W. E. Zion Church

TO TAP

Sanitary

SEWER ON THE

West

OF

2nd St. S. W.

AVE.

ST. TYPE (F STREET

Blacktop

THE PREMISES BEING LOT NO.

1078-1079-Pl 1079

HOUSE NO.

209

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTIONS OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR


Liane

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

4-25-85

ST. JAMES A.M.E CHURCH

SANITARY SEWER
CREW INVESTIGATING
SEWER BACK UP IN
CHURCH FOUND BACK
FLAP VALVE IN 6"
SANITARY SEWER LATERAL



BACK FLAP VALVE

CREW REPAIRED VALVE
TOLD THEM TO INFORM
CHURCH THAT VALVE
WAS THE CHURCH'S RESPONSIBILITY