



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9329

MAIN LINE Broke Down W/H
4" LATERAL connected to MAIN G"
101.5' SOUTH OF DEADEND MAIN
UP Stream

DATE INSPECTED 10-25-79

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1027 & 29

SIZE OF PIPE USED 6" MAIN & 4" LAT.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? REPAIRED


WAS ATTACHED TO MAIN @ MAIN

NAME OF CONTRACTOR D. A. L. Breat


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

29 & 1027

AM Her



THIS POINT 6" MAIN
WAS BROKEN &
REPAIRED
6' DEEP



SIGNED Leroy H. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS Installed short 4" pipe & 6" X 4" X 2' Long wye

N^o 9329

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, October 25

RECEIVED OF Louis P. Snyder

FEE OF \$ 25.00

FOR WHICH PERMISSION IS GRANTED Robert R.

TO TAP Sanitary

SEWER ON THE West 12th

OF Goodrich Rd. N.E.

AVE.

ST. TYPE OF STREET City of Massillon

THE PREMISES BEING LOT NO. 6999

HOUSE NO. 1029-1029

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Robert R.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.