Nº 9343

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-21-579	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
was lateral at curb? 10	NAME OF CONTRACTOR Juck
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
7'AT HOUSE 24' PIPE 9'AT LOUSE 24' PIPE 9'AT LOUSE 24' PIPE BEHIND HICKORY AUE N.E	ROM WEST CORNER OF HOUSE TICKORY AVE NIE CURB
SIGNED AND MAN MAN	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 9343

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

· :		MASSI	LON, OHIO, Z	= 12
RECEIVED OF	JACOB	GLICE		FEE OF \$257.
FOR WHICH PERMISSION IS GR	ANTED	1 1008	GLICK	
TO TAP SANITHE	<u> </u>	SEWER ON	THE 500	TH.
OF HICKORY	G	VE. ST. TYPE CF S	TREET CASE	1 SE14C
THE PREMISES BEING LOT NO.	14056	W 50-10 W 40 40 00 40 00 40 40 40 40 40 40 40 40	, HOUSE NO	1909
WORK TO BE DONE IN ACCORD		ICE NO. 19-1:	971 DULY PASSED B	Y THE CITY COUNCIL, AND RI
NAME OF CONTRACTOR	JACOB	GLIC	K	

7 sù .

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.