FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2337	
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH CURB LINE AND DEPTH	
WAS LATERAL AT CURB? TO SOME THE SOME T	
WAS ATTACHED TO MAIN 120 NAME OF CONTRACTOR & COLOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
STONER NIG N BEHIND CURB SIGNED William Windows FILED AT ENGINEER'S OFFICE Inspector for City HOUSE II II & GARAGE 30 FROM NEST CORNER 510 PLOSE FROM NEST CORNER 570 NER NIG N 6 FROM LA SIGNED William Windows Inspector for City	

Nº 9351

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, URAL. 27			
RECEIVED OF JOYAN	Kanousk	9	FEE OF \$2216	
FOR WHICH PERMISSION IS GRANTED	134.4	GROUPE		
то тар	SEWER ON TH	1E		
of <u>576/084</u>	AVE.	EET (2013) 155.	<u>Sens</u>	
OF	# T	, HOUSE NO	37	
WORK TO BE DONE IN ACCORDANCE WITH ORE OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19-197	DULY PASSED BY THE CITY	COUNCIL, AND RI	
NAME OF CONTRACTOR 75 1	- HEDRE	no any mang any		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.