

✓
Nº 9352

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-15-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

220'

HOUSE NO. 1533

SIZE OF PIPE USED 6" CAST IRON

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

220'

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Haldeman

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

11' FROM HOUSE

EAST CORNER
OF HOUSE

6' DEEP AT HOUSE

16' FROM CENTER OF STREET TO C.

38' OVER TO BREAK IN PIPE

(M) 220' DOWNSTREAM 8' OF PIPE REPLACED CAST I

SIGNED William W. Winton
Inspector for City

FILED AT ENGINEER'S OFFICE

N

REMARKS

6 21
No 9352

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Feb 8, 1

RECEIVED OF

H. G. Schuler

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Holderbaum

TO TAP

Repair

SEWER ON THE

South

OF

Walnut St. S.W.

AVE.

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

8836

HOUSE NO.

1533

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Holderbaum

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.