

8-

Nº 9362

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-14-80 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 329
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR East 30
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



22' FROM WEST CORNER OF BUILD.

48' IN FROM CURB TO WHERE SEWER W
PLUG

SIGNED William W. Wadsworth FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS House torn down

COT. OFF

Nº 9362

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 11

RECEIVED OF

East 30 Plumbing

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

William Washington

COT. OFF

TO TAP

Sanitary

SEWER ON THE

South

OF

Duluth Ave. S.E.

AVE.

ST. TYPE OF STREET

Cast & Steel

THE PREMISES BEING LOT NO.

9423

HOUSE NO.

329

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTIONS OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

East 30

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.