

7-



Nº 9363

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-20-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1809

SIZE OF PIPE USED

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

East 50

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

William Windom

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

House is torn down

CUT-OFF

Nº 9363

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 18

RECEIVED OF

~~FIVE DOLLARS~~ EAST 30

FEE OF

\$5.

FOR WHICH PERMISSION IS GRANTED

~~CITY OF MASSILLON, OHIO~~ GLASS CRAW

CUT-OFF

TO TAP

SEWERS

SEWER ON THE

SOUTH

OF

LINCOLN WAY EAST

AVE.

ST. TYPE OF STREET

ASPHALT

THE PREMISES BEING LOT NO.

10406

HOUSE NO.

1809

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

EAST 30

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.