FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N^{\underline{0}}$

9367

DATE INSPECTED $5-5-80$ HOUSE NO. 840	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	ı
WAS ATTACHED TO MAIN 220 SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR $BEAUEREXCAUATING$.L OF BUILDING SERVED.
	77' FROM SEWER to CURB GOING 81 TO EAST SIDE OF HOUSE
	4' TO FENCE ON NORTH SIDE OF NEXT LOOK
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS House Eggs dozus	

CUT-UFF

№ 9367

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

1043 WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RU

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.