

Nº 9372

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-20-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 871

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Windom
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

House torn down

WEST
OF
ERTLE

2-26
3-7

CUT-OFF

Nº 9372

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASCILLON, OHIO, May 13

RECEIVED OF Beaver Excavating FEE OF \$ 5.⁰⁰

FOR WHICH PERMISSION IS GRANTED Scott Miller

CUT-OFF Sanitary TO TAP West SEWER ON THE

OF 1st St. N.E. AVE. ST. TYPE OF STREET Hard Layfare

THE PREMISES BEING LOT NO. 5141 HOUSE NO. 821

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaver

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.