

Nº 9389

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

8-27-80

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

320

SIZE OF PIPE USED

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

William Windom

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

House torn down

cut off
No 9389

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *August 27*
RECEIVED OF *H & W. Contractors Inc.* FEE OF \$ *5.*
FOR WHICH PERMISSION IS GRANTED *H & W. Contractors Inc.*
Cut off Sanitary TO TAP SEWER ON THE *East*
11th St. S.W. AVE. ST. TYPE OF STREET *Chip & Seal*
THE PREMISES BEING LOT NO. *3127-B*, HOUSE NO. *320*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H & W. Contractors Inc.

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.