

5



FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9391

DATE INSPECTED 9-23-80

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 83'

HOUSE NO. 802

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR PLAZ

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



83' TO CURB ↑ 32' IN FROM MANHOLE ← TREMONT S.E.

SIGNED William W. [Signature] Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9391

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 22*

RECEIVED OF

Edgar L. Hering

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Edgar Hering

TO TAP

Sanitary

SEWER ON THE

11th St

OF

Lumant Ave. 16th

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

9498

HOUSE NO.

802

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Plas & Co.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.

Luis