9396 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N^{\underline{0}}$

DATE INSPECTED 10-21-80	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
House No	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.

SIGNED William	Mudo.	FILED AT ENGINEER'S	S OFFICE
Insp	ector for City		
1 /		$\pm A$	
1 / / / / / / / / / / / / / / / / / / /	a marketing	Jan	
REMARKS	L C Comme		

2. 43

№ 9396

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

•

	MASSILLON, OHIO, Oct 20
RECEIVED OF	FEE OF 9) 10 7
FOR WHICH PERMISSION IS GRANTED CITY OF	Maccillor
COT-087 1 + 1	VER ON THE Vactor
OF Lacuse J. J. M. AVE. ST. TYP	E (F STREET DAY & WILL
THE PREMISES BEING LOT NO. 12490	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
NAME OF CONTRACTOR 4.8 W.	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.