FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

 $N_{\overline{0}}$

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 12 2 3
HOUSE NO7	<u> </u>
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 12 DEEP 2
WAS LATERAL AT CURB? YES	in the second se
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIAMA
, , , ,	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
SOUTH AUS., S.W.	
122.3' = = = = = = = = = = = = = = = = = = =	145.4
Q' Y Y Y Y Y Y Y Y Y	
107-109	
	And the second s
SIGNED W. WINDOM	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS THIS INFORMATION TAKE	N FRAM INSPECTOR'S VAGUE SMETCH - EJ. IV.

OFFICE OF THE DIRECTOR OF PUBLIC SER 9405 IT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A: C. Deana

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.