

N^o 9417

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-26-81

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2026

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 246' EAST OF MH 9' DEEP
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR OAKES

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9417

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 20

RECEIVED OF *Home of Tradition, Inc.* FEE OF \$ *25.*

FOR WHICH PERMISSION IS GRANTED *Home of Tradition, Inc.*

TO TAP *Sanitary* SEWER ON THE *North*

OF *Dumont Ave. S.E.* AVE. *City & Loc.*
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *6211*, HOUSE NO. *2026*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *G. Baker*

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.