

CSA

9423

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-16-81

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1606

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


SIZE OF PIPE USED

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



CON. FLOOR LEFT IN



SIGNED W.M.D. Leung

Inspector for City

FILED AT ENGINEER'S OFFICE 1-16-81

REMARKS Tore Down ON My Day Off

CUT-OFF

Nº 9423

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO,

RECEIVED OF

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.