

Nº

9439

✓
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

16-

DATE INSPECTED

6-25-81

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

116' WEST OF M 8' DEER

HOUSE NO.

1415

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

No


WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 9439

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

June 19

RECEIVED OF

Haldubaum

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Haldubaum

TO TAP

Sanitary

SEWER ON THE

South

OF

Summit Ave. S.E.

AVE.

ST. TYPE OF STREET

Radburn

THE PREMISES BEING LOT NO.

6155

HOUSE NO.

1615

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldubaum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.