Nº 9447 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16-5-81	IF SO HOW AND LOCATION FROM 140' South of MH 6'D	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR HOLDER BAUM	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	300B 1	
	161110	
SIGNED William Hamm	FILED AT ENGINEER'S OFFICE	
/ Inspector for City		
REMARKS		

№ 9447

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Sett.	
DESCRIPTION OF THE STATE OF THE	Marian	FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Much	el D'Mange	·
TO TAP Sampans SE	() = 0 -	
TAKIN'S built	YPE OF STREET Condition	Te
THE PREMISES BEING LOT NO. O. h 406		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR / Aldrikaum	<u>ب</u>	
,		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.