## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

16-1=

DATE INSPECTED 4 - 2 - 82 HOUSE NO. 1706	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN-STREAM
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  DOWN-STREAM TO DITCH AT 43' WEST OF 174 6' DEEP  CURB LINE AND DEPTH
WAS LATERAL AT CURB7	Bunkett
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIAMA
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
N	43°
SIGNED William Leanny Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9457

ß,

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, G	OHIO, April	
RECEIVED OF F	Bunkett		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Office Lub	٠	
TO TAP	SEWER ON THE	- Must	<u> </u>
of Marga furta and	AVE.	Chip A	live C
THE PREMISES BEING LOT NO. 631		HOUSE NO. 170	0 6
WORK TO BE DONE IN ACCORDANCE WITH ORD OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19,1971	DULY PASSED BY THE C	HTY COUNCIL, AND
NAME OF CONTRACTOR	With		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.