

Nº 9458 ✓✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

REPAIR

DATE INSPECTED 4-12-89

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 434

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR A J DIANA E RICKERSON

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS REPAIR

N^o 9458

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, APRIL 12

RECEIVED OF _____ FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED A. J. DIANA

TO TAP SANITARY SEWER ON THE EAST

OF HARMON PL. N.E. AVE.
ST. TYPE OF STREET ASPH, CHIP T SEAL

THE PREMISES BEING LOT NO. 1393, HOUSE NO. 434

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. DIANA

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**