

Nº 9467 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-10-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

REPAIR

HOUSE NO. 1613

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR Holder Baum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9467.

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 7*

RECEIVED OF *Holderbaum*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Holderbaum*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Walnut Rd SW*

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *10357*

HOUSE NO. *1613*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Holderbaum*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**