

Nº 9471

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10: ✓

DATE INSPECTED 6-21-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 221

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 84' NORTH of MH 8' DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

→ N



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 9471

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 12, 1971 8.

RECEIVED OF Hardman

FEE OF \$ 1.00

FOR WHICH PERMISSION IS GRANTED REPAIR

TO TAP Sanitary

SEWER ON THE West

OF 25th St SE

AVE.

ST. TYPE OF STREET City

THE PREMISES BEING LOT NO. 10453

HOUSE NO. 221

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hardman

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**