

N^o 9475 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7-3 ✓

DATE INSPECTED 7-13-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 141

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

154' NORTH OF MH 8'DEEP


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



154'

SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9475

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO,

July 13

RECEIVED OF

Robert Strick

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Robert Strick

TO TAP

Sanitary

SEWER ON THE

West

OF

27th St. E.

AVE.

ST. TYPE OF STREET

Chap & Oak

THE PREMISES BEING LOT NO.

3680

HOUSE NO.

141

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldubrum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.