## Nº 9486 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

-		
	_	

DATE INSPECTED 9-17-82	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.2117	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 40 WESTOFH TDEEP CURB LINE AND DEPTH
WAS LATERAL AT CURB?	1
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	Parameter 1
	1 a 3 · 1)
	47:1
	College and Colleg
	6€ +10' = <del>1</del>
SIGNED William Man	
SIGNED MANAGEMENT Inspector for City	MULL FILED AT ENGINEER'S OFFICE

Nº 9486

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	OHIO, Jug. 12,
RECEIVED OF Distor	<u> Co</u>	FEE OF \$ 25
f	Mar Co	
FOR WHICH PERMISSION IS GRANTED		
to TAP	SEWED ON THE	South
TO TAP	SEVER ON THE	
of Cambridge and S.E.	AVE. ST. TYPE OF STREET	Chipf Seal
THE PREMISES BEING LOT NO	138	2117
THE PREMISES BEING LOT NOZ_Z_Z	<u> </u>	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH O OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	of Jue	<del></del>
Note: This permit cover	rs work outside o	of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.