

Nº 9492

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

7-17 ✓

DATE INSPECTED 9-16-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 919

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

187' WEST OF MH 2' DEEP

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR EASWALE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED:



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9492

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

82

MASSILLON, OHIO, SEPT 2

RECEIVED OF JIM COVEY FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED LASURE EXCAVATING

TO TAP SANITARY SEWER ON THE SOUTH

OF OVERLOOK AVE SW AVE. ST. TYPE OF STREET CHURCH SEAL

THE PREMISES BEING LOT NO. 11304, HOUSE NO. 919

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR LASURE EXCAVATING

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.