Nº 9502 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-5-82	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 730	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? Y 5 5	NAME OF CONTRACTOR LOS & Los
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
· •	LAYERAITE GENCIUS
SIGNED William Hammer Inspector for City	FILED AT ENGINEER'S OFFICE CHUB

Nº 9502

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 26	
RECEIVED OF LACT LACK FEE OF \$	23
FOR WHICH PERMISSION IS GRANTED ROOF CRUIC	
FOR WHICH PERMISSION IS GRANTED	
TO TAP da water Sewer ON THE Cast	
OF American It A W AVE. ST. TYPE OF STREET PROGRAMMED	
THE PREMISES BEING LOT NO. $0.6.432$, House No. 130	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, OF THE DEPARTMENT OF PUBLIC SERVICE.	AND
NAME OF CONTRACTOR July July	
Note: This permit covers work outside of building only. Any wo	ork

walls of building is subject to Massillon Board of Health Regulations.