Nº 9510

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-18-83 HOUSE NO. 2236	IF SO HOW AND LOCATION FROM 79'49 STAKAM 8'DEEP FIRST MANHOLE DOWN STREAM 79'49 STAKAM 8'DEEP
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR CATCHILL
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
off was a	
• • • • • • • • • • • • • • • • • • •	
ريم درج	79' 0
SIGNED William Hanner Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 9510

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	, оню, - Упи С	,
RECEIVED OF CITAL	En String	FEE OF \$-	<u>5</u>
FOR WHICH PERMISSION IS GRANTED			
TO TAB			
of / N F	AVE. ST. TYPE OF STREE	<del>п</del>	
THE PREMISES BEING LOT NO. 43	37	_, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH	H ORDINANCE NO. 19.1971		, AND
NAME OF CONTRACTOR CATTLE			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.