FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-10-83	IF SO HOW AND LOCATION FROM WALL 137
House No	,
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	M_{01} . T
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MAINTAVITE
TAG ATTAGETED TO THE TELEPOOR	<i>y</i>
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
•	1 2 411'-71
	$I_{ijk}V$
	1 ³⁵ /
	1
•	. 1 📆
	1901
	1 251 /32'
•	
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	,

Nº 9527

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u>Vienedan</u>	<u> </u>
RECEIVED OF Linder Carne	Ĩ4	<u> </u>	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Carrier and a		. <u></u>
TO TAPSE	WED ON THE	There	The second
OF Sections And 19 AVE. ST. TY	WER ON THE	Chyp &	Lel
THE PREMISES BEING LOT NO	, Hous	E NO	76
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR MILITARIE TO			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.