

✓✓
Nº 9530

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-27-82

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1765 DORM

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN N/E

NAME OF CONTRACTOR Schmitt

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9530

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 24

RECEIVED OF

Salmon Plumbing & Heating Inc.

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Manuelon Baptist Temple

TO TAP

Sanitary

SEWER ON THE

South

OF

Casper Dr. S.W.

AVE.

ST. TYPE OF STREET

Chapel Hill

THE PREMISES BEING LOT NO.

O. L. 788

HOUSE NO.

1365

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Salmon

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**