## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-27-83 HOUSE NO. 622	IF SO HOW AND LOCATION FROM 159' South of M. 310
SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 15-5	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	A 3'
	150 5 450
SIGNED William Ramon	23,0
SIGNED WALLAND inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 9537

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

I	MASSILLON, OHIO, AUG 10
KORT	RECEIVED OF (1) RUSCELLET (HARRES OF TRANSPORT) FEE OF \$ 20
	FOR WHICH PERMISSION IS GRANTED
	TO TAPSEWER ON THE
·	AVE. OFST. TYPE OF STREET
	THE PREMISES BEING LOT NO. 11288, HOUSE NO. 622
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
317.101 <b>4</b>	NAME OF CONTRACTOR 131201 AF TRADITIONS  OAK CS
11 A	Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.