

9542

DATE INSPECTED 9-2-83

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1930

SIZE OF PIPE USED _____


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH-----

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN 10/14/

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9542

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

983

Bus

EAST

FACE

MASSILLON, OHIO, August 30,

RECEIVED OF Fidelity Motor Bus Line FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Fidelity Motor Bus Line

TO TAP Sanitary SEWER ON THE 19TH ST NE

OF E 19TH ST NE AVE. ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 0.1 # 22, HOUSE NO. 1920 UNCL.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

CAV

NAME OF CONTRACTOR PLAS EXCAVATING

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.