

Nº 9543

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-12-83

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 718

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

125' North of MH-3'D

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 9543

OFFICE OF THE DIRECTOR OF PUBLIC SEE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 7

RECEIVED OF Fruit Savings & Loan

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Fruit Savings & Loan

TO TAP Sanitary

SEWER ON THE East

OF 3rd St

AVE.

ST. TYPE OF STREET City & Sub

THE PREMISES BEING LOT NO. F39

, HOUSE NO. 718

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Heldrichman

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**