№ 9573

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED / - 37 - 84	_ IF SO HOW AND LOCATION FROM	
HOUSE NO	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	OURD LINE AND DEL TITLE CONTROL OF THE PROPERTY OF THE PROPERT	
WAS LATERAL AT CURB?	- H & U/	
WAS ATTACHED TO MAIN NAME OF CONTRACTOR $\mathcal{H} \notin \mathcal{U}$ SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
CYTOFFIN BASEMENTON NORTH WALL		
/		
SIGNED Willam Han	FILED AT ENGINEER'S OFFICE	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
REMARKS	***************************************	

CUT-OFF

No LOCATION WM. D.

Nº 9573

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, AAN 18
RECEIVED OF RECEIVED	
	CUT UM SEWOR
CVT-OFF	sewer on the
of Lumout ane. I.W.	
THE PREMISES BEING LOT NO. 3186	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINA OF THE DEPARTMENT OF PUBLIC SERVICE.	ANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR SE	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.