

Nº 9576

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-25-84

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 900

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 38'
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

38' North of MH 9' DEEP

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N 4



SIGNED

William Hamme
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9576

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, FEB. 23

RECEIVED OF RALPH T & ROSE M. HARRIS FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED RALPH T & ROSE M. HARRIS

TO TAP SANITARY SEWER ON THE EAST

OF PRINCE HOEN CIRCLE AVE. ST. TYPE OF STREET ASPHALT

THE PREMISES BEING LOT NO. 11786, HOUSE NO. 900

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR SCHIAER EXCAV.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.