

N^o

9581

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-9-84

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1335

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



REPAIR

SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REPAIR

N^o 9581

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 9 - 84

RECEIVED OF Walden FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Owner

REPAIR
TO TAP Sanitary SEWER ON THE West

OF Heaven Rd. S.E. AVE.
ST. TYPE OF STREET Driveway

THE PREMISES BEING LOT NO. 12667, HOUSE NO. 1335

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Walden

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**