Nº ∫ 9588

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT. CURB LINE AND DEPTH	
WAS-LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
SIGNED NO INSPECTION	/ FUED AT ENGINEER'S OFFICE	
Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 9588

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, A MASSILLON, OHIO, OHIO, A MASSILLON, OHIO, OH		
RECEIVED OF James 711 6 8	June 1	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED.	me for		
EVT-UFF January SE	WER ON THE 6 4 7	<u>f</u>	
OF 4 H ST. T	YPE OF STREET	Get Alp	
THE PREMISES BEING LOT NO		28	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO THE DEPARTMENT OF PUBLIC SERVICE.	IO. 19.1971 DULY PASSED	BY THE CITY COUNCIL, AND	
NAME OF CONTRACTOR Dimme	*. 		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.