№ 9589

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
SIGNED NO INSPECT	FILED AT ENGINEER'S OFFICE			
Inspector for Cli	ry _			
REMARKS				

Nº 9589

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON,	OHIO, Afred	<u> </u>
RECEIVED OF Beauty EX	egueteta		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Middenson	<u> </u>	
· · · · · · · · · · · · · · · · · · ·			
COTAP RESIDENT	SEWER ON THE	والإنجاز المراجع	
of	AVE. _ ST. TYPE OF STREE	TRbyand_	andare
THE PREMISES BEING LOT NO. 7753			<i>;</i>
WORK TO BE DONE IN ACCORDANCE WITH ORDIN			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR BEAUTY			
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.