## Nº 9593 ✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
	CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
	NAME OF CONTRACTOR

SIGNED	NO	INSPECTION Inspector for City	I	FILED A	T ENGINEER'S	OFFICE	
REMARKS							

outert № | 9593

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, April 27
RECEIVED OF Columb	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Janon H.
CUT OF P JANUARY SE	NER ON THE Coat
OF 9 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•
THE PREMISES BEING LOT NO. 3212	<b>'</b>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	
OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.