Nº 9615 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED July 12, 1984	IF SO HOW AND LOCATION FROM Wye of 234
HOUSE NO. 2808	/
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 9' DepTh 2541 CURB LINE AND DEPTH 9' DepTh 2541
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Holder Davin
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR // O/O/O/O/O/O/O/O/O/O/O/O/O/O/O/O/O/
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	
Back Back	I ERST OF ElecTRICAL MCTER
SIGNED Inspector for City	filed at engineer's office
REMARKS	

Nº 9615

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON,	оню,
RECEIVED OF		FEE OF \$
FOR WHICH PERMISSION IS GRANT	FED	
TO TAP	SEWER ON THE_	
	and the second of the second	<u>A de</u>
THE PREMISES BEING LOT NO		HOUSE NO. 2 10 K
WORK TO BE DONE IN ACCORDANG		DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	1-1 128 11 12 12 15 15 15 15 15 15 15 15 15 15 15 15 15	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

Nº 9612

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED JUNE, 21, 1984	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1124	types a
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH (6/FT. 10 in. 6/FT.5/in To Tap) 9FT 10 in From CURB
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. J. DIANA
SHOW BY DIAGRAM RELATION OF LATERAL TO W	ALL OF BUILDING SERVED.
SIGNED WARE SIGNED WAS Inspector for Ch	North CONNEX N.E. EAST CONNEX N.E.
REMARKS	