

✓
✓
Nº 9618

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED July 12, 1984

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Wye PT 90'

HOUSE NO. 2809

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

9' depth 90'


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



↓
N

SIGNED

Harold Searcy
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 9618

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 13

RECEIVED OF Gen. Paster

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED Gen. Paster

TO TAP Drainage

SEWER ON THE Lot

OF Anderson Ave. N.W.

AVE.

ST. TYPE OF STREET Drainage

THE PREMISES BEING LOT NO. 0.4.178 (1)

HOUSE NO. 2829

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Heldman

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**