

№ 9622

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED August 1, 1984

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Goes in Manhole

HOUSE NO. 426

SIZE OF PIPE USED 4" Iron


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 4 FT Deep

WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Harold Searles
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS Used Iron Wye and Pipe From Building out 5 FT,

H.R.

REPAIR

N^o 9622

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS PERMIT TO TAP SEWER

MASSILLON, OHIO,

Aug. 1

RECEIVED OF

Heldbaum

FEE OF \$

2.40

FOR WHICH PERMISSION IS GRANTED

Copper Cup

TO TAP

From 1st St.

SEWER ON THE

East

OF

1st St. W. P.C.

AVE.

ST. TYPE OF STREET

Blair St.

THE PREMISES BEING LOT NO.

1895

HOUSE NO.

426

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Heldbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**