Nº 9625 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED September, 12,1984	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 604		
SIZE OF PIPE USED CUT-OFF	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR GIEN TISSOT	
WAS ATTACHED TO MAIN		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	7 Desp ₹ N	
and the state of t	14=50'> /3	
<u> </u>	And the second s	
Throld Jerina	FILED AT ENGINEER'S OFFICE	
SIGNED / Inspector for City		
()		
REMARKS CEMENT FIGUR DRAIN AND CLEAN-OUT		

CUTTER

9625

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Tag 77,
RECEIVED OF Cathill Lucking	FEE OF \$
FOR WHICH PERMISSION IS GRANTED 1	to Tour & Will .
CUT-050 August 5 SKATLED	wer on the Most
OF TRANSPORT OF ST. TY	
THE PREMISES BEING LOT NO. 2438	/
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.	D. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR CATTILL	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

1235