

Nº 9640

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

INSPECTOR _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

LOST ORIGINAL PERMIT
INFORMATION TAKEN FROM STC
ISSUED TO PAUL E HOFFMAN
1223 CHERRY RD. N.W. O.L. 90

SIGNED _____

10-3-84

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Contractor - SCHAER